

SPECIALITY RESTAURANT 7-6(E7OU) Location # 334188



Sign at main entrance does not meet 210.b.(2)

Phone number for local emergency services (911 where available) and the public road used to access the site Not posted on battery sign.

SPECIALITY RESTAURANT 7-6(E7OU) Location # 334188



Well sign

SPECIALITY RESTAURANT 7-6(E7OU)

Location # 334188



Old derelict labels on tank.

Tank is labeled for Condensate and Produced water.
Contents stenciled as Production water.

SPECIALITY RESTAURANT 7-6(E7OU)
Location # 334188



Contents stenciled as Production water.



Contents stenciled as Production water.

SPECIALITY RESTAURANT 7-6(E7OU)
Location # 334188



Weeds on lease road at entrance of location.



Sediment build up in ditch.

SPECIALITY RESTAURANT 7-6(E7OU)
Location # 334188



Weeds on lease road.

SPECIALITY RESTAURANT 7-6(E7OU)
Location # 334188



**Erosion and sediment movement of drainage ditch
around location perimeter.**

SPECIALITY RESTAURANT 7-6(E7OU)
Location # 334188



**Erosion and sediment movement of drainage ditch
around location perimeter.**

SPECIALITY RESTAURANT 7-6(E7OU) Location # 334188



Erosion and sediment movement of drainage ditch around location perimeter.



Erosion and sediment movement of drainage ditch around location perimeter.

SPECIALITY RESTAURANT 7-6(E7OU)

Location # 334188



Washing and riling running on to location.

SPECIALITY RESTAURANT 7-6(E7OU)

Location # 334188



Erosion damage from run off behind separator and meter house.



Erosion damage from run off behind separator and meter house.

SPECIALITY RESTAURANT 7-6(E7OU)
Location # 334188



Culvert under road.
N 39.36538 W-108.15607



Culvert inlet needs maintained.

SPECIALITY RESTAURANT 7-6(E7OU)
Location # 334188



Subsidence of road shoulder at culvert.

SPECIALITY RESTAURANT 7-6(E7OU)
Location # 334188



Derelict waddles in ditch along culvert.



Derelict waddles in ditch along culvert.