

# Inspection Photos

08/26/2019

Operator: D90 ENERGY LLC # 10706

Location ID: 435480

Lincoln County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: D90 ENERGY LLC # 10706  
Location ID: 435480



**Photo 1:** Photo taken from the south end of the location, facing west. Photos 1-3 provide an overview of the location from west, to north, to east. Photo also show the perimeter stormwater ditch on the location

**Photo 2:** See comments under photo 1.

Inspection Photos  
Operator Name: D90 ENERGY LLC # 10706  
Location ID: 435480



**Photo 3:** See comments under photo 1.



**Photo 4:** Photo taken from the perimeter fence on the south end of the location, facing southeast. Photo shows erosion degradation and sediment deposition due to sediment laden stormwater runoff from the location. Photo shows a headcut is beginning to form. 6 foot measuring stick for reference.

## Inspection Photos

Operator Name: D90 ENERGY LLC # 10706

Location ID: 435480



**Photo 5:** Photo south end of the location, facing northwest. Photo shows where perimeter stormwater ditch ends. Photo shows sufficient stormwater BMPs to allow for sediment laden free stormwater discharge from the location remains missing. Photo shows areas of sediment deposition that leads to the adjacent lands.



**Photo 6:** Photo taken from the south end of the pad. Photo shows stormwater erosion degradation on the location remains evident.

Inspection Photos  
Operator Name: D90 ENERGY LLC # 10706  
Location ID: 435480



**Photo 7:** Photo taken from the southwest end of the location, facing north. Photo shows perimeter stormwater ditch.



**Photo 8:** Photo taken from the perimeter stormwater ditch on the west end of the location. Photo shows stormwater erosion degradation on the location and sediment deposition into the ditch. No BMPs have been placed at the end of the ditch to prevent sediment from transporting off location.

Inspection Photos  
Operator Name: D90 ENERGY LLC # 10706  
Location ID: 435480



**Photo 9:** Photo taken from the north end of the location, facing north. Photo shows erosion degradation remains evident on the access road.



**Photo 10:** Continued from photo 9. Photo shows erosion degradation remains evident on access road and no BMPs have been installed.

Inspection Photos  
Operator Name: D90 ENERGY LLC # 10706  
Location ID: 435480



**Photo 11:** See comments under photo 10



**Photo 12:** Photo taken from the sign at the location entrance. Photo shows sign identifying tanks on the location, their capacity and their contents. D90 has indicated that the were provided approval from inspector Sherman, that this signage will be sufficient per Rule 210.d.