

**Inspection Photos**  
**Location Name: A.D. Jeffers A#1**  
**Location ID: 323176**



**Photo 1 WH sign**



**Photo 2 WH and stained soil in front of PU**



**Inspection Photos**  
**Location Name: A.D. Jeffers A#1**  
**Location ID: 323176**



**Photo 3 Stained soil around WH and PU base**



**Photo 4 Mechanical Issue: PU gear box appears to be leaking**

**Inspection Photos**  
**Location Name: A.D. Jeffers A#1**  
**Location ID: 323176**



**Photo 5 Stained soil on PU base from what appears to be leaking gear box**



**Photo 6 Stained soil around and underneath PU motor.**

**Inspection Photos**  
**Location Name: A.D. Jeffers A#1**  
**Location ID: 323176**



**Photo 7 Stained soil around WH and PU base**



**Photo 8 Sep/meter run and ECD**

**Inspection Photos**  
**Location Name: A.D. Jeffers A#1**  
**Location ID: 323176**



**Photo 9 TNK BTRY sign faded and not legible. NFPS placards faded and not legible.**



**Photo 10 Stained soil outside crude oil tank berm.**