

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/27/2019

Submitted Date:

08/27/2019

Document Number:

693501192

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
318501 \_\_\_\_\_ Silver, Randy \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: \_\_\_\_\_ 46290 \_\_\_\_\_  
Name of Operator: KP KAUFFMAN COMPANY INC \_\_\_\_\_  
Address: 1675 BROADWAY, STE 2800 \_\_\_\_\_  
City: \_\_\_\_\_ DENVER \_\_\_\_\_ State: \_\_\_\_\_ CO \_\_\_\_\_ Zip: \_\_\_\_\_ 80202 \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 12 \_\_\_\_\_ Number of Comments  
5 \_\_\_\_\_ Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	<a href="#">All inspections</a>
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241422	WELL	PR	03/20/1995	OW	123-09211	ROBERT G BURGE 2	PR

**General Comment:**

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign not legible		
Corrective Action:	Install sign to comply with Rule 210.e.		Date: 09/27/2019
Emergency Contact Number:			
Comment:	Sign not legible		
Corrective Action:	Install sign to comply with Rule 210.e.		Date: 09/27/2019
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil: stained soil around WH		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.		Date: 09/27/2019
Type	WEEDS		
Comment:	Weeds in and around PU, electric panel and on location.		
Corrective Action:	Comply with rule 603 f		Date: 09/10/2019
Type	OTHER		
Comment:	Mechanical Issue: 1" flow line on WH appears to be leaking		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 09/27/2019
Overall Good: <input type="checkbox"/>			

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Square tubing		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			

Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 241422 Type: WELL API Number: 123-09211 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>                      On Monday August 27, 2019 at approximately 11:13 AM, I, Inspector Randy Silver, conducted an on-site inspection at KP Kauffman site Robert G Burg #2, at API # 05-123-09211 in Weld County Colorado.                      While there, I observed production well site                      During this inspection the following possible compliance issues were observed:                      Weeds: Rule 603 f Corrective action date of 9-10-19 See photos 1,2,4,5                      Stained soil: Rule 907 e Corrective action date of 9-27-19 See photo 3                      Well Head sign: Rule 210 e Corrective action date of 9-27-19 See photo 2                      Mechanical issue: Rule 605 d Corrective action date of 9-27-19 see photo 3                      At time of inspection well site appears not to have been maintained, weeds are overgrown in and around PU, Electric panel and location. Well head sign is faded and not legible. 1" flow line valve appears to be leaking causing the stained soil around well head.                      Weather conditions: Clear and location is dry.                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	silverr	08/27/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693501193	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4922591">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4922591</a>