

Inspection Photos

Loc#446527

Operator: Sandridge

Inspection Number: 692401283

Inspection Date: 8/15/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southwest.

August 15, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Pintail Loc#446527



Photo#2: 6/27/19
Erosion initiating on Southwest corner of Cut slope

Photo#3: 8/15/19
Erosion initiating on Southwest corner of Cut slope.

August 15, 2019



Photo#4: 6/27/19

BMPs have failed; erosion occurring on Southeast corner of cut slope.



Photo#5: 8/15/19

BMPs have failed; erosion occurring on Southeast corner of cut slope.

August 15, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Pintail Loc#446527



Photo#6:

Cellars of Wells were filled with what appears to be water topped with skim of Oily waste and other possible pollutants.

Photo#7:

Cellars of Wells were filled with what appears to be water topped with skim of Oily waste and other possible pollutants.

August 15, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Pintail Loc#446527