

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/21/2019

Submitted Date:

08/21/2019

Document Number:

699300038**FIELD INSPECTION FORM**
 Loc ID 317669 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Medina, Justin		justin.medina@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
,		cogcc@kpk.com	All Inspections
Pesika, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239749	WELL	PR	09/19/1972	OW	123-07537	NORMAN W. YURK 1	PR

General Comment:

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Placard is peeling		
Corrective Action:	Install sign to comply with Rule 210.e	Date:	10/12/2018
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	barb wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric control panel, transformers		
Corrective Action:		Date:	

Type: Bradenhead	# 1	
Comment:	appears to be plumbed to surface	
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:	Gas Meter was last calibrated in 2007.	
Corrective Action:	Measure gas per Rule 329.	Date: 10/12/2018

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	PBV FIBERGLASS		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shared with crude oil tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.098270,-104.870720
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--

Inspected Facilities

Facility ID: 239749 Type: WELL API Number: 123-07537 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>On Tuesday 8/21/19 at approximately 12:30 pm, I, Inspector Robbie Revas, per Doc. # 691401027</p> <p>Conducted an on-site follow up inspection at the Norman W. Yurk # 1 KP Kauffman, at API # 05-123-07537 in Weld County Colorado.</p> <p>While there, I observed a Producing Well site,</p> <p>During this inspection the following possible compliance issues from Doc. # 69140107 have not been addressed:</p> <p>Measurement of gas: Measure gas Per Rule 329. It appears that the Gas meter has not been calibrated since 12/17/07. See Attached photo #4</p> <p>Signs and Markers general condition: Crude Oil Tank placard is peeling. See attached photo #5</p> <p>Weather is sunny and hot, Location is dry.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing education COGCC Inspection Report Summary</p>	revasr	08/21/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402152150	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4916203
699300039	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4916198