



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type PIT

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Equipment:**

corrective date

Type: Bradenhead # 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Ancillary equipment # 2

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Flaring:**

Type

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Inspected Facilities**

Facility ID: 89212 Type: WELL API Number: 071-06792 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
THIS IS A FOLLOWUP INSPECTION TO INSP. DOC# 687902544. CORRECTIVE ACTION FOR ANCHOR MARKER HAS BEEN ADDRESSED. THE CORRECTIVE ACTION FOR SI WELL WITH NO MIT WAS INACCURATE ACCORDING TO PRODUCTION RECORD ON FILE THE WELL WAS NEVER SI FOR 2 YEARS.	beardsit	08/26/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695101235	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4922943">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4922943</a>