

Inspection Photos
Location Name: Energy Minerals Unit B1
Location ID: 318873



Photo 1 WH sign has new sticker installed



Photo 2 WH and weeds have been removed

Inspection Photos
Location Name: Energy Minerals Unit B1
Location ID: 318873



Photo 3 Weeds on access road have been cut



Photo 4 Crew cutting weeds at time of inspection

Inspection Photos
Location Name: Energy Minerals Unit B1
Location ID: 318873



Photo 5 Crew on site cutting weeds and starting to remove small stained soil spots



Photo 6 Crew tried to start removing strained soil from spill around produced water tank.

Inspection Photos
Location Name: Energy Minerals Unit B1
Location ID: 318873



Photo 7 Stained soil around crude oil tank.



Photo 8 North crude oil tank states in multiple spots OUT OF SERVICE

Inspection Photos
Location Name: Energy Minerals Unit B1
Location ID: 318873



Photo 9 Stained soil and mechanical issue 2" load lines on crude oil tank.



Photo 10 Stained soil and mechanical issue crude oil load line and inspection hatch

Inspection Photos
Location Name: Energy Minerals Unit B1
Location ID: 318873



Photo 11 Crew cleaning stained soil under recirc pump



Photo 12 Stained soil under piping in separator

Inspection Photos
Location Name: Energy Minerals Unit B1
Location ID: 318873



Colorado Oil and Gas Conservation Commission
Aug 28, 2019 10:32:50

Photo 13 mechanical issue piping inside separator house appears to be leaking causing stained soil.



Colorado Oil and Gas Conservation Commission
Aug 28, 2019 10:33:34

Photo 14 TNK BTRY