

Inspection Photos
Location Name: MOUNTAIN JAY 31-19
API#: 05-071-06579
INSP. #: 695101252



PHOTO 1: WELLHEAD

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: MOUNTAIN JAY 31-19

API#: 05-071-06579

INSP. #: 695101252



PHOTO 3: EROSION DOWN GRADE FROM CULVERT AT THE ENTRANCE OF ROW, STORMWATER EROSION HAS EXPOSED WHAT APPEARS TO BE A GAS GATHERING LINE. **Install or repair required BMPs per Rule 1002.f. CA DATE 9-28-19**

PHOTO 4: EROSION ON UP GRADE SIDE OF MAIN ROW SOUTH OF LOCATION ROW ENTRANCE. **Install or repair required BMPs per Rule 1002.f. CA DATE 9-28-19**

Inspection Photos

Location Name: MOUNTAIN JAY 31-19

API#: 05-071-06579

INSP. #: 695101252



PHOTO 5: EROSION DOWN GRADE SIDE OF MAIN ROW SOUTH (UP THE HILL) OF LOCATION ROW ENTRANCE. Install or repair required BMPs per Rule 1002.f. CA DATE 9-28-19

PHOTO 6: VIEW OF ANOTHER ARE OF EROSION ON UP GRADE SIDE OF MAIN ROW SOUTH OF LOCATION ROW ENTRANCE. Install or repair required BMPs per Rule 1002.f. CA DATE 9-28-19

Inspection Photos

Location Name: MOUNTAIN JAY 31-19

API#: 05-071-06579

INSP. #: 695101252



PHOTO 7: VIEW OF ANOTHER ARE OF EROSION ON UP GRADE SIDE OF MAIN ROW SOUTH OF LOCATION ROW ENTRANCE. **Install or repair required BMPs per Rule 1002.f. CA DATE 9-28-19**

PHOTO 8: CULVER IS PLUGGED. **Install or repair required BMPs per Rule 1002.f. CA DATE 9-28-19**