

# *Inspection Photos*

*Loc#416625*

*Operator: Sandridge*

*Inspection Number: 692401287*

*Inspection Date: 8/16/19*





Photo#1:  
Overview of Location.

August 16, 2019



Photo#2:  
Newly installed silt fence failed.



Photo#3:  
Newly installed silt fence failed.

August 16, 2019




**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Surprise Damfino Loc#416625



Photo#4:  
Erosion of stockpile.



Photo#5:  
Erosion of stockpile.

August 16, 2019



Photo#6:  
Further sloughing and erosion of Cut is occurring.

August 16, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Surprise Damfino Loc#416625



Photo#7:  
Stormwater is improperly ponding on East side of site.

August 16, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Surprise Damfino Loc#416625