

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/28/2019

Submitted Date:

08/28/2019

Document Number:

699300059

**FIELD INSPECTION FORM**

Loc ID 317951 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Findings:**

- 21 Number of Comments
- 8 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Pesika, Conor		conor.pesicka@state.co.us	
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240242	WELL	SI	06/01/2019	OW	123-08030	MAHONEY-PERRIN 1	SI

**General Comment:**

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Sign is adequate, Placards are faded. They are still legible at time of inspection but will need replaced in the near future.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil at PJ base		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	09/30/2019
Type	WEEDS		
Comment:	Weeds growing on location		
Corrective Action:	Comply with Rule 603.f	Date:	09/09/2019
Type	TRASH		
Comment:	unused material in Compressor shed		
Corrective Action:	Comply with Rule 603.f	Date:	09/09/2019
Type	OTHER		
Comment:	Stained soil in Compressor shed		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	09/30/2019
Type	OTHER		
Comment:	Stained soil around WH		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	09/30/2019
Type	TRASH		
Comment:	unused corrugated tin on location		
Corrective Action:	Comply with Rule 603.f	Date:	09/09/2019
Type	OTHER		
Comment:	Hammer union appears to be leaking		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	09/30/2019

Type	OTHER			
Comment:	Unmarked risers			
Corrective Action:	Comply with Rule 603.f . 24 hrs for LOTO on risers		Date:	09/30/2019

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>				
Type	OTHER			
Comment:	Electrical transformers, breaker panel and meter. Barb wire			
Corrective Action:			Date:	
Type	PUMP JACK			
Comment:	Barbe wire			
Corrective Action:			Date:	

<b>Equipment:</b>				corrective date
Type: Ancillary equipment	# 2			
Comment:	Electrical transformers, breaker panel and meter.			
Corrective Action:			Date:	
Type: Compressor	# 1			
Comment:				
Corrective Action:			Date:	
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:			Date:	
Type: Prime Mover	# 1			
Comment:	Electric motor			
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:	Appears to be plumbed to surface			
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:			Date:	
Type: Vertical Heated Separator	# 1			
Comment:	Appears SI			
Corrective Action:			Date:	

Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

**Flaring:**

Type	
Comment:	

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 240242 Type: WELL API Number: 123-08030 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Wednesday 8/28/19 at approximately 11:30 am, I, Inspector Robbie Revas, conducted an on-site inspection at The Mahoney-Perrin #1 KP Kauffman, at API #05-123-08030 in Weld County Colorado.                      While there, I observed a Shut in well and tank battery.                      During this inspection the following possible compliance issues were observed:                      Stained soil around WH Rule 907.e Remove or Remediate Stained soil. CA date 9/30/2019 See photo #5 Loc. Pics                      Stained soil a PJ base Rule 907.e Remove or Remediate Stained soil. CA date 9/30/2019 See photo #6 Loc. Pics                      Weeds growing on location Rule 603.f CA date 9/9/2019 See photo # 7 Loc. Pics                      Stained soil in Compressor shed Rule 907.e CA date 9/30/19 Photo #4 Tank battery pics                      Unmarked flow line risers: Rule 603.f 24 hrs. to LOTO 30 days to remove riser CA date 9/30/2019                      See Photos #5 &amp; #6 Tank battery pics                      Mechanical issue: 605.d Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at Regular intervals and maintain in good mechanical condition. CA date 9/30/2019 See photo #9 Tank battery pics                      Trash: Unused material corrugated tin on location Rule 603.f CA date 9/9/2019 See photos #7 &amp; #8 Tank battery pics                      Trash: unused material in compressor shed Rule 603.f CA date 9/9/2019 See photo # 10 Tank battery pics                      Location is dry and weather is clear.                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.                      Continuing education COGCC Inspection Report Summary                      Inspection.                      This is a summary of inspection report.</p>	revasr	08/28/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300060	Location pics.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4924072">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4924072</a>
699300061	Tank battery pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4924073">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4924073</a>