

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/22/2019

Submitted Date:

08/22/2019

Document Number:

699300048**FIELD INSPECTION FORM**

Loc ID 317739 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
Pesika, Conor		conor.pesicka@state.co.us	
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239894	WELL	PR	05/26/1973	OW	123-07682	CARL A MILLER A 2	PR

General Comment:

Location				
Lease Road:				
Type	Access			
comment:	Weeds growing down access road to wellsite			
Corrective Action	Comply with Rule 603.f			Date: 09/05/2019
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	At time of inspection wellhead sign is legible but faded. Emergency contact number is barely legible. No corrective action at this time but sign will need addressed soon.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Weeds are growing tall around wellsite ROW			
Corrective Action:	Comply with Rule 603.f			Date: 09/05/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input checked="" type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Angle Iron			
Corrective Action:				Date:
Type	OTHER			
Comment:	Electrical transformers, breaker panel and meter. Steel bar			
Corrective Action:				Date:
Equipment:				
Type: Pump Jack	# 1			corrective date
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	Appears to be plumbed to surface			
Corrective Action:				Date:
Type: Ancillary equipment	# 1			

Comment:	Electrical transformers, breaker panel and meter.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric Motor		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 239894 Type: WELL API Number: 123-07682 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 8/22/19 at approximately 10:30 am, I, Inspector Robbie Revas, Conducted an on-site inspection at the Carl A. Miller A #2 KP Kauffman, at API #123-07682 in Weld County Colorado.</p> <p>While there, I observed Producing Well</p> <p>During this inspection the following compliance issues were observed:</p> <p>Housekeeping: Weeds growing tall down access road to wellsite and growing tall around wellsite ROW,</p> <p>Comply with Rule 603.f Corrective action date 9/5/19. See attached photos #1, #3, #4 and #5</p> <p>Wellhead sign is beginning to fade and will need to be replaced in the near future but is adequate at time of this inspection see attached photo #2.</p> <p>A follow up on this site inspection will need to be conducted to ensure that the compliance issues have been corrected to comply with COGCC Rules. Location is dry and weather is clear and sunny</p> <p>Continuing education COGCC Inspection Report Summary</p> <p>Inspection.</p> <p>This is a summary of inspection report.</p>	revasr	08/22/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402153349	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4917276
699300049	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4917271