

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2019

Submitted Date:

08/29/2019

Document Number:

689703473

**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 311577      LONGWORTH, MIKE      2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER      State: CO      Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6      Number of Comments

2      Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name      | Phone | Email                                     | Comment                   |
|-------------------|-------|---|---------------------------|
| Kellerby, Shaun   |       | shaun.kellerby@state.co.us                |                           |
| , Caerus Piceance |       | COGCC.inspections@caerus<br>oilandgas.com | Piceance inspections only |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 211034      | WELL | PR     | 03/16/2004  | GW         | 045-06792 | FEDERAL 6204  | PR          |

**General Comment:****COGCC Inspection Report Summary**

On 08/27/2019 at approximately 1500 hrs, I, Inspector Mike Longworth, conducted a field inspection at Caerus FEDERAL # 6204

Location # 311577 in Garfield County, Colorado

During this inspection the following possible compliance issues were observed:

Dead weed debris.

Maintain housekeeping and base permeability.

C.A. Date 09/08/2019

Dead weed debris on location and in tank berm.

Comply with Rule 603.f.

C.A. Date 09/08/2019

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☒**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

**Emergency Contact Number:**

|                    |     |             |
|--------------------|-----|-------------|
| Comment:           | 911 |             |
| Corrective Action: |     | Date: _____ |

**Good Housekeeping:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | DEBRIS   |       |            |
| Comment:           | Dead weed debris on location and in tank berm. |       |            |
| Corrective Action: | Comply with Rule 603.f.                        | Date: | 09/08/2019 |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE         | 1 | 400 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type     | Capacity          | Permeability (Wall) | Permeability (Base) | Maintenance |
|----------|-------------------|---------------------|---------------------|-------------|
| Earth    | Adequate          | Walls Sufficient    | Base Insufficient   | Inadequate  |
| Comment: | Dead weed debris. |                     |                     |             |

|                    |  |       |            |
|--------------------|--|-------|------------|
| Corrective Action: | Maintain housekeeping and base permeability. | Date: | 09/08/2019 |
|--------------------|--|-------|------------|

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities |                |                       |            |                  |
|----------------------|----------------|-----------------------|------------|------------------|
| Facility ID: 211034  | Type: WELL     | API Number: 045-06792 | Status: PR | Insp. Status: PR |
| Producing Well       |                |                       |            |                  |
| Comment:             | Producing well |                       |            |                  |
| Corrective Action:   |                |                       |            | Date:            |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            |                         |                       |               |                          |         |
| Compaction       | Pass            |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                    | URL   |
|--------------|--------------------------------|---|
| 689703477    | Inspection 689703473 photo log | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4924696">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4924696</a> |