

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/20/2019

Submitted Date:

08/29/2019

Document Number:

688800613

FIELD INSPECTION FORM

Loc ID 333983 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 5Name of Operator: COLORADO OIL & GAS CONSERVATIONAddress: 1120 LINCOLN ST SUITE 801City: DENVER State: CO Zip: 80203**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Heil, John		john.heil@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298285	WELL	SI	06/15/2015	OBW	007-06264	FOSSET GULCH MW 34-5-14 1	EI
298286	WELL	SI	06/15/2015	OBW	007-06265	FOSSET GULCH MW 34-5-14 2	EI

General Comment:

On August 20, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Fosset Gulch MW 34-5-14 #1 and #2. For the most recent field inspection report of this facility, please refer to document #688800203. The purpose of this site visit was to replace the desiccants within the equipment enclosures, ensure that all equipment on site was secure, and check for leaks at the well heads.

Location			
Lease Road:			
Type	Main		
comment:	Location is road side along Forest Service Road 613.		
Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Location signs mounted to protective barricades surrounding well heads. Township in well name is incorrect. Legal description on sign is accurate.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Sign mounted to protective barricade surrounding ancillary equipment.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Monitor weeds during the growing season.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Steel pipe protective barricade fencing surrounding well heads and ancillary equipment.		
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Ancillary equipment	# 1		
Comment:	In-Situ Troll Net Hub with 2 pressure transducers deployed in each well.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:			Date:
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 298285 Type: WELL API Number: 007-06264 Status: SI Insp. Status: EIFacility ID: 298286 Type: WELL API Number: 007-06265 Status: SI Insp. Status: EI**COGCC Comments**

Comment	User	Date
<p>On August 20, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Fosset Gulch MW 34-5-14 #1 and #2. For the most recent field inspection report of this facility, please refer to document #688800203. The purpose of this site visit was to replace the desiccants within the equipment enclosures, ensure that all equipment on site was secure, and check for leaks at the well heads. Eight desiccant packets and one Desi-tube were replaced during this site visit. The desiccants were last replaced on 7/6/18. The Desi-tube and the desiccant packets were near exhaustion. None of the battery terminals appeared to have any corrosion. Neither of the well heads had any visible signs of leaks.</p>	hughesjo	08/29/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800614	Inspection Photos 8.20.19	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4925271