

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/20/2019

Submitted Date:

08/29/2019

Document Number:

688800615

**FIELD INSPECTION FORM**

Loc ID 334009 Inspector Name: Hughes, Jim On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 5Name of Operator: COLORADO OIL & GAS CONSERVATIONAddress: 1120 LINCOLN ST SUITE 801City: DENVER State: CO Zip: 80203**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name  | Phone | Email                    | Comment |
|---------------|-------|--------------------------|---------|
| Fischer, Alex |       | alex.fischer@state.co.us |         |
| Heil, John    |       | john.heil@state.co.us    |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name        | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 299319      | WELL | SI     | 06/15/2015  | OBW        | 007-06270 | HWY 151 34-4-30 MW 2 | EI          |
| 299320      | WELL | SI     | 06/15/2015  | OBW        | 007-06271 | HWY 151 34-4-30 MW 1 | EI          |

**General Comment:**

On August 20, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Hwy. 151 34-4-30 #1 and #2 MW. For the most recent field inspection report of this facility, please refer to document #688800457. The purpose of this site visit was to replace the desiccants within the equipment enclosures, ensure that all equipment on site was secure, and check for leaks at the well heads.

| <b>Location</b>  |  |        |                 |
|--|--|--------|-----------------|
| Overall Good: <input type="checkbox"/>                 |  |        |                 |
| <b>Signs/Marker:</b>                                   |  |        |                 |
| Type   | WELLHEAD   |        |                 |
| Comment:   | Signs posted near entrance to location.                                  |        |                 |
| Corrective Action:                                     |  |        | Date:           |
| Emergency Contact Number:                              |  |        |                 |
| Comment:   | Sign mounted to stock panel enclosure.                                   |        | Date: _____     |
| Corrective Action:                                     |  |        |                 |
| <b>Good Housekeeping:</b>                              |  |        |                 |
| Type   | WEEDS  |        |                 |
| Comment:   | Monitor weeds during growing season.                                     |        |                 |
| Corrective Action:                                     |  |        | Date:           |
| Overall Good: <input type="checkbox"/>                 |  |        |                 |
| <b>Spills:</b>   |  |        |                 |
| Type   | Area   | Volume |                 |
| In Containment: No                                     |  |        |                 |
| Comment:   |  |        |                 |
| <input type="checkbox"/> Multiple Spills and Releases? |  |        |                 |
| <b>Fencing/:</b>                                       |  |        |                 |
| Type   | WELLHEAD   |        |                 |
| Comment:   | Stock panel enclosure around both well heads and ancillary equipment.    |        |                 |
| Corrective Action:                                     |  |        | Date:           |
| <b>Equipment:</b>                                      |  |        |                 |
| Type: Ancillary equipment # 1                          |  |        | corrective date |
| Comment:   | Telemetry equipment.   |        |                 |
| Corrective Action:                                     |  |        | Date:           |
| Type: Ancillary equipment # 1                          |  |        |                 |
| Comment:   | In-Situ Troll Net Hub with 2 pressure transducers deployed in each well. |        |                 |
| Corrective Action:                                     |  |        | Date:           |
| <b>Venting:</b>  |  |        |                 |
| Yes/No   |  |        |                 |
| Comment:   |  |        |                 |
| Corrective Action:                                     |  |        | Date:           |
| <b>Flaring:</b>  |  |        |                 |
| Type   |  |        |                 |
| Comment:   |  |        |                 |
| Corrective Action:                                     |  |        | Date:           |

**Inspected Facilities**

|                            |                   |                              |                   |                         |
|----------------------------|-------------------|------------------------------|-------------------|-------------------------|
| Facility ID: <u>299319</u> | Type: <u>WELL</u> | API Number: <u>007-06270</u> | Status: <u>SI</u> | Insp. Status: <u>EI</u> |
|----------------------------|-------------------|------------------------------|-------------------|-------------------------|

|                            |                   |                              |                   |                         |
|----------------------------|-------------------|------------------------------|-------------------|-------------------------|
| Facility ID: <u>299320</u> | Type: <u>WELL</u> | API Number: <u>007-06271</u> | Status: <u>SI</u> | Insp. Status: <u>EI</u> |
|----------------------------|-------------------|------------------------------|-------------------|-------------------------|

**COGCC Comments**

| Comment  | User     | Date       |
|--|----------|------------|
| <p>On August 20, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Hwy. 151 34-4-30 #1 and #2 MW. For the most recent field inspection report of this facility, please refer to document #688800457. The purpose of this site visit was to replace the desiccants within the equipment enclosures, ensure that all equipment on site was secure, and check for leaks at the well heads. Eight desiccant packets and one Desi-tube were replaced during this site visit. The desiccants were last replaced on 7/6/18. The Desi-tube and the desiccant packets were all near exhaustion. None of the battery terminals appeared to have any corrosion. Neither of the well heads had any visible signs of leaks.</p> | hughesjo | 08/29/2019 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description               | URL   |
|--------------|---------------------------|---|
| 688800616    | Inspection Photos 8.20.19 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4925289">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4925289</a> |