

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/29/2019

Submitted Date:

08/29/2019

Document Number:

689703481

FIELD INSPECTION FORM
 Loc ID 335059 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
23	WELL	PR	06/30/2006	GW	045-11671	PUCKETT PA 331-35	PR
24	WELL	PR	12/16/2005	GW	045-11672	PUCKETT PA 431-35	PR
36	WELL	PR	12/16/2005	GW	045-11675	PUCKETT PA 332-35	PR
37	WELL	PR	12/16/2005	GW	045-11676	PUCKETT PA 432-35	PR
39	WELL	PR	12/16/2005	GW	045-11677	PUCKETT PA 532-35	PR
210896	WELL	PR	12/01/2010	GW	045-06654	ARCO GV 56-35	PR
282143	WELL	PR	12/19/2005	GW	045-11688	PUCKETT PA 32-35	PR

General Comment:**COGCC Inspection Report Summary**

On Thursday 08/29/2019 at approximately (1500 hrs), I, Inspector Mike Longworth, conducted a field inspection at Terra ARCO # GV 56-35, at Location # 335059 in Garfield County, Colorado

During this inspection the following possible compliance issues were observed:

No battery sign at battery.

Install sign to comply with Rule 210.b.

C.A. Date 10/30/2019

Labels on 80 bbl produced water tank need replaced.

Install sign to comply with Rule 210.d.

C.A. Date 10/30/2019

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Labels on 80 bbl produced water tank need replaced.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/30/2019
Type	BATTERY		
Comment:	No battery sign at battery.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	10/30/2019

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Type	SEPARATOR				
Comment:					
Corrective Action:				Date:	

Equipment:				corrective date
Type: Ancillary equipment	# 1			
Comment:	Chemical container at wells			
Corrective Action:				Date:
Type: Bird Protectors	# 5			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 7			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 7			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	200 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	<100 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	23	Type:	WELL	API Number: 045-11671	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	24	Type:	WELL	API Number: 045-11672	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	36	Type:	WELL	API Number: 045-11675	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	37	Type:	WELL	API Number: 045-11676	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	39	Type:	WELL	API Number: 045-11677	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	210896	Type:	WELL	API Number: 045-06654	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	282143	Type:	WELL	API Number: 045-11688	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
				Material Handling And Spill Prevention	Pass	
		Culverts	Pass			
Check Dams	Pass					
		Compaction	Pass			
Gravel	Pass					
		Gravel	Pass			
Ditches	Pass					
Compaction	Pass					
		Ditches	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689703482	Inspection 689703481 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4925325