

MARALEX RESOURCES, INC.– 53255
API# 05-045-06288 USA #1-24DF
Inspection Date : 8/28/2019



Location overview looking S.



Wellhead with fence and sign - Temporarily Abandoned.

MARALEX RESOURCES, INC.– 53255
API# 05-045-06288 USA #1-24DF
Inspection Date : 8/28/2019



Separator overgrown with vegetation.



Partially buried tank with no berms or labels. Overgrown with vegetation

MARALEX RESOURCES, INC.– 53255
API# 05-045-06288 USA #1-24DF
Inspection Date : 8/28/2019



Pit with livestock fencing. Overgrown with vegetation.



Unused riser in fenced area. Not locked out/tagged out. No blind flange on open end.

MARALEX RESOURCES, INC.– 53255
API# 05-045-06288 USA #1-24DF
Inspection Date : 8/28/2019



Multiple unused risers. Not locked out/tagged out. No blind flange on open end



Unused riser in fenced area.