

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/28/2019

Submitted Date:

08/29/2019

Document Number:

693801053

**FIELD INSPECTION FORM**

Loc ID 322423 Inspector Name: BROWNING, CHUCK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
14 Number of Comments  
5 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 OGCC Operator Number: 53255  
 Name of Operator: MARALEX RESOURCES INC  
 Address: P O BOX 338  
 City: IGNACIO State: CO Zip: 81137

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Kellerby, Shaun		shaun.kellerby@state.co.us	
Ried, Jordan	970-563-4000	maralextechjr@gmail.com	All Inspections
Graves, Jim	970-858-8550	mrinc20@qwestoffice.net	Operations Manager
,		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210462	WELL	SI	04/27/2012	GW	045-06218	DRY FORK FEDERAL 1-29	TA

**General Comment:**

COGCC staff performed a followup field inspection on 8/28/2019. Followup to inspection doc#689702947 on 03/29/2019 Issues were found requiring corrective action. CAs from previous inspection not completed. See inspection text and photos for details. Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location			
<b>Lease Road:</b>			
Type	Main		
comment:	Cr200		
Corrective ActionL			Date:
Type	Access		
comment:	Access through private ranch road.		
Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Install sign to comply with Rule 210.d. CA from previous inspection not completed. CA date remains the same as previous inspection.		Date: 07/01/2016
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	970-858-8550 / 911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Flowline risers not LO/TO or marked are considered unused equipment		
Corrective Action:	Comply with Rule 603.f . For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.		Date: 09/02/2019
Type	WEEDS		
Comment:	Location and equipment is overgrown with vegetation.		
Corrective Action:	Comply with Rule 603.f . CA from previous inspection not completed. CA date remains the same as previous inspection.		Date: 07/01/2016
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PIT		
Comment:	Hog wire & T-post		
Corrective Action:			Date:

Type	WELLHEAD		
Comment:	Square tube		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	PBV STEEL		39.417877,-108.462481
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	No Berms			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1). CA from previous inspection not completed. CA date remains the same as previous inspection.			Date: 04/15/2019

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 210462 Type: WELL API Number: 045-06218 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID:      Lat: 39.417617      Long: -108.462400

Reference Point: SE      Other: \_\_\_\_\_      Length: 30      Width: 30

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type: Livestock      Fencing Condition: Adequate

Comment:

Corrective Action

Date:

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date:

Anchor Trench Present: \_\_\_\_\_      Oil Accumulation: NO      2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693801061	Inspection photos 8/28/2019	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4925331">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4925331</a>