

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402093660

Date Received:

07/12/2019

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10611

Name of Operator: LONGS PEAK RESOURCES LLC

Address: 2727 ALLEN PARKWAY SUITE 1850

City: HOUSTON State: TX Zip: 77019

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Angie Galvan

281-713-4635

angie.galvan@boomtownoil.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 693700195

Inspection Date: 06/14/2019

FIR Submit Date: 06/17/2019

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: LONGS PEAK RESOURCES LLC

Company Number: 10611

Address: 2323 S SHEPHERD SUITE 1150

City: HOUSTON State: TX Zip: 77019

### LOCATION - Location ID: 438066

Location Name: Railay West Number: 2833-1NH County: \_\_\_\_\_

Qtrqr: NENW Sec: 28 Twp: 12N Range: 66W Meridian: 6

Latitude: 40.985330 Longitude: -104.784320

### FACILITY - API Number: 05-123-00 Facility ID: 438066

Facility Name: Railay West Number: 2833-1NH

Qtrqr: NENW Sec: 28 Twp: 12N Range: 66W Meridian: 6

Latitude: 40.985330 Longitude: -104.784320

### CORRECTIVE ACTIONS:

1 ☒ CA# 126165

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Handle diesel impacted material in accordance with Rule 907A. This is not E&P Exempt Waste. Provide proper secondary containment as required for non-highway diesel ASTs in accordance with Rule 1002.f.(2).

Date: 07/14/2019

Response: CA COMPLETED

Date of Completion: 07/01/2019

Operator Comment: All diesel impacted material has been scraped, contained, removed, and disposed of by Pawnee Waste Landfill. All valves, pipes, and fittings have been securely fastened. Containment has been installed, see Photo 1.

COGCC Decision: Approved via an AMI

COGCC  
Representative:

**2** ☒ CA# 126166

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 07/14/2019

Response: CA COMPLETED

Date of Completion: 07/01/2019

Operator Comment: All valves, pipes and fittings have been repaired and securely fastened. The produced water and oil ASTs have been cleaned, see Photo 2 and 3.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**3** ☒ CA# 126167

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Handle any oily impacted material in accordance with Rule 907.e.

Date: 07/14/2019

Response: CA COMPLETED

Date of Completion: 07/01/2019

Operator Comment: Water produced loadout lines have been repaired and the soil has been scraped and contained and disposed of by Pawnee Waste Landfill. The area was remediated with new pea gravel, see Photo 4.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**4** ☒ CA# 126168

Corrective Action: Operator shall submit a Form 19 Supplemental Report within 60 days that includes a site map of spill extents and areas excavated, a map of confirmation soil sample locations and laboratory analytical results for all soil samples collected from the location. Soil confirmation samples shall be analyzed for TVPH and TEPH (C6-C36), benzene, ethylbenzene, toluene and total xylenes. Operator shall provide a reclamation plan for restoration of area excavated and equipment two track developed offsite.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 07/09/2019

Operator Comment: Soil samples are scheduled to be taken 7/12. A Form 19 Supplemental Report will be submitted prior to 60 days of the date of the primary filing.

COGCC Decision: Approved

COGCC  
Representative:

**5** ☒ CA# 126169

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 07/14/2019

Response: CA COMPLETED

Date of Completion: 07/09/2019

Operator Comment: Rills have been corrected and BMP's are in place to prevent rilling and degradation. Maintenance has been done to the location. Berms have been installed on west, south, and east side of the location for runoff control. Rip rap will be installed to prevent rills and washes.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Angie Galvan

Signed: \_\_\_\_\_

Title: Regulatory

Date: 7/12/2019 9:01:21 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402093660	FIR RESOLUTION SUBMITTED
402106197	Photos

Total Attach: 2 Files