

Inspection Photos
Location Name: TELNA 24-22 TR
API#: 05-071-08304
INSP. #: 695101297



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN



Inspection Photos

Location Name: TELNA 24-22 TR

API#: 05-071-08304

INSP. #: 695101297



PHOTO 3: AREA OF IMPACTED SOIL AROUND WELLHEAD. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 9-29-19

PHOTO 4: UNUSED EQUIPMENT STORED ON LOCATION. REMOVE UNUSED EQUIPMENT, COMPLY WITH RULE 603.f. CA DATE 9-29-19

Inspection Photos

Location Name: TELNA 24-22 TR

API#: 05-071-08304

INSP. #: 695101297



**PHOTO 5: UNUSED EQUIPMENT (1" RISER). REMOVE
UNUSED RISER, COMPLY WITH RULE 603.f. FOR
UNUSED EQUIPMENT AND NTO FOR UNUSED
RISERS. CA DATE 9-29-19.**