

**Inspection Photos**  
**Location Name: Chevron Wilson Creek**  
**CE&P Facility ID 149002**



**Location 149002**



**Fence in disrepair along access road.**



**Inspection Photos**  
**Location Name: Chevron Wilson Creek**  
**CE&P Facility ID 149002**



**Fence in disrepair along northern side of the Facility.**



**Liner pieces in land treatment cell.**



**Inspection Photos**  
**Location Name: Chevron Wilson Creek**  
**CE&P Facility ID 149002**



**Liner pieces along northern side of Facility.**



**Liner pieces and barbed wire roll along northern side of Facility.**



**Inspection Photos**  
**Location Name: Chevron Wilson Creek**  
**CE&P Facility ID 149002**



**Fluid and apparent hydrocarbon accumulation in the northeast corner of the Facility.**



**Vehicular entrance into the Facility.**



**Inspection Photos**  
**Location Name: Chevron Wilson Creek**  
**CE&P Facility ID 149002**



**Wind rowed treatment cell.**



**Evidence of livestock accessing Facility.**