

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/03/2019

Submitted Date:

09/03/2019

Document Number:

699300074

**FIELD INSPECTION FORM**
 Loc ID 317489 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Barber, Matt		mbarber@hpres.com	<a href="#">All Inspections</a>
Gomez, Jason		jason.gomez@state.co.us	
Pesika, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
238228	WELL	SI	07/01/2017	GW	123-05061	SHOE 1	SI

**General Comment:**

### Location

<b>Lease Road:</b>			
Type	Access		
comment:	Weeds overgrown on access Rd.		
Corrective Action	Comply with Rule 603.f	Date:	09/13/2019

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Information inaccurate at well(s) or battery. Form 10 was submitted on 5/1/2019 and is in process.		
Corrective Action:	Install sign to comply with Rule 210.b. 30 days if missing 24 hour operator contact number and/or local emergency contact. 60 days for all others.	Date:	
Type	BATTERY		
Comment:	Information inaccurate at well(s) or battery, Form 10 was submitted on 5/1/2019 and is in process		
Corrective Action:	Install sign to comply with Rule 210.b. 30 days if missing 24 hour operator contact number and/or local emergency contact. 60 days for all others.	Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 500px; height: 20px;" type="text"/>	
Corrective Action:	<input style="width: 500px; height: 20px;" type="text"/>	Date: <input style="width: 100px;" type="text"/>

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	WH packing appears to be leaking		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 30 days unless leak is found. Immediate call to operator if leak is found and 24 hours to fix the leak or isolate leak.	Date:	10/03/2019
Type	WEEDS		
Comment:	Weeds overgrown on entire location, around WH, TB, Heated Horizontal Separator, Gas meter run.		
Corrective Action:	Comply with Rule 603.f	Date:	09/13/2019
Type	OTHER		
Comment:	WH packing appears to be leaking.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 30 days unless leak is found. Immediate call to operator if leak is found and 24 hours to fix the leak or isolate leak.	Date:	10/03/2019

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Steel pole		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barb wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appearsto be plumbed to surface		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Inspector Name: Revas, Robbie

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 238228 Type: WELL API Number: 123-05061 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Well appears to be SI

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 9/3/2019 at approximately 1000 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at the Shoe #1KP Kauffman, at API # 05-123-05061 in Weld County Colorado.</p> <p>While there, I observed SI well and Tank battery. Scout card show it to be SI and it appears SI. See photos #7, 8 and 9.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Housekeeping: Weeds overgrown on access road, and throughout well site location.</p> <p>Rule 603.f CA date 9/13/2019 see attaches photos #2, 3, 4, 5, 6 and 10.</p> <p>Mechanical conditions: Wellhead packing appears to be leaking, securely fasten all valves, pipes and fittings to ensure good mechanical conditions inspect at regular intervals and maintain.</p> <p>Rule 605.d 30 days unless leak is found then 24 hrs. To repair or isolate the leak.</p> <p>10/3/2019</p> <p>WH sign and TB sign still show Highpoint Resources and their emergency number. The form 10 was submitted on 5/1/2019 and is in process KP Kauffman should replace signs immediately so proper information is at wellsite See attached photo #1 and 2.</p> <p>Location is dry, weather is cloudy.</p> <p>I spoke with Brad Kotrell with Highpoint Resources at approximately 1025 am and let him know what I observed and he informed me that KP Kauffman had recently purchased this site. I called KP Kauffman emergency number and spoke with Janette at approx. 1040 am she took down the information and said she would relay it to the on call representative and have him give me a call to go over what I observed Lease operator Jerry Sheldon arrived on location at 1115 hrs. and I went over what I observed and showed him and he said that they were going to get it tightened up and work on plumbing to get it back online.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	09/03/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300075	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4927617">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4927617</a>