

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/03/2019

Submitted Date:

09/03/2019

Document Number:

699300076

**FIELD INSPECTION FORM**
 Loc ID 329979 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

11 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesika, Conor		conor.pesicka@state.co.us	
,		cogcc@kpk.com	All Inspections
Gomez, Jason		jason.gomez@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250331	WELL	SI	12/01/2017	GW	123-18134	HSR CHURCH 14-17	SI

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Weeds growing over access road.		
Corrective Action:	Comply with Rule 603.f	Date:	09/13/2019

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	No Wellhead sign: A CA was assigned to this well on 5/16/2019 per doc. # 685100952, Form 10 submitted on 05/01/2019 so at the time of previous inspection it was within the rules of 210.b. Form 10 is at time of this inspection is in process Doc. # 402018972. WH sign is now out of compliance and needs to be installed.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	10/03/2019

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil under crude oil tank valve		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	10/03/2019
Type	WEEDS		
Comment:	Weeds growing throughout location and TB loc.		
Corrective Action:	Comply with Rule 603.f	Date:	09/13/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		

Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLs	FIBERGLASS AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares with crude oil tanks				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:



**Inspected Facilities**Facility ID: 250331 Type: WELL API Number: 123-18134 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Appears to be SI

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

## Comment

## User

## Date

**COGCC Inspection Report Summary**

On Tuesday 9/3/2019 at approximately 1300 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at the HRS Church 14-17 KP Kauffman, at API # 05-123-18134 in Weld County Colorado.

While there, I observed SI well and Tank battery. Scout card show it to be SI and it appears SI.

During this inspection the following possible compliance issues were observed:

Housekeeping: Weeds overgrown on access road, and throughout well site and TB location.

Rule 603.f CA date 9/13/2019 see attaches photos #2, 3, 4, 7 and 8.

Housekeeping: Stained soil under Crude oil tank valve. Comply with rule 907.e CA date 10/3/2019

See attached photo #6.

WH sign hasn't been installed TB sign is adequate. The form 10 was submitted on 5/1/2019 and is in process KP Kauffman should install WH sign immediately so proper information is at wellsite See attached photo #1 and 2.

Location is dry, weather is cloudy.

A follow up on this site inspection needs to be conducted to ensure the

Compliance issues have been corrected to comply with COGCC rules.

Continuing education COGCC Inspection Report Summary.

This is a summary of inspection report.

revasr

09/03/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300077	Loc pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4927618">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4927618</a>