

# Inspection Photos

09/03/2019

Operator: BAYSWATER EXPLORATION &  
PRODUCTION LLC - 10261

Location ID: 433247

Washington County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 433247



**Photo 1:** Photo taken from the location, facing northwest. Photo shows starting point for the **disturbance area** transect. Photo shows vegetation over the disturbance area.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 433247



**Photo 2:** Photo of the 50<sup>th</sup> point for the **disturbance area** transect, facing northeast. Photo shows vegetation over the disturbance area.



## Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 433247



**Photo 3:** Photo of the 50<sup>th</sup> point for the **disturbance area** transect, facing southwest. Photo shows vegetation over the disturbance area.



## Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 433247



**Photo 4:** Photo of the 50<sup>th</sup> point for the **disturbance area** transect. Photo shows vegetation over the disturbance area.



## Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 433247



**Photo 5:** Photo taken from the location, facing southeast. Photo shows end point for the **disturbance area** transect. Photo shows vegetation over the disturbance area.



## Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 433247



**Photo 6:** Photo taken from the adjacent reference area, facing east. Photo shows starting point for the **reference area** transect. Photo shows vegetation over the reference area.

## Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 433247



**Photo 7:** Photo of the 50<sup>th</sup> point for the **reference area** transect, facing south. Photo shows vegetation over the reference area.



## Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 433247



**Photo 8:** Photo of the 50<sup>th</sup> point for the **reference area** transect, facing north. Photo shows vegetation over the reference area.



## Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 433247



**Photo 9:** Photo of the 50<sup>th</sup> point for the **reference area** transect. Photo shows vegetation over the reference area.



## Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 433247



**Photo 10:** Photo taken from the adjacent reference area, facing west. Photo shows the end point for the **reference area** transect. Photo shows vegetation over the reference area.

## Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 433247



**Photo 11:** Photo taken from the access road, facing east. Photo shows large sections of the access road remains bare and exposed soil.

