

Location Name: Foundation Energy Management – Sooner Unit - Pit ID 112069
Inspection Date: 08/28/2019



Photo # 1 – Partially buried oil slim tank with inadequate secondary containment on north side of Pit ID 112069

Location Name: Foundation Energy Management – Sooner Unit - Pit ID 112069
Inspection Date: 08/28/2019



Photo # 2 – Culvert (tin horn) requiring closure under an approved eForm 27.





Photo # 3 – Petroleum impacted soil near culvert (tinhorn) requiring closure under an approved eForm 27.

Location Name: Foundation Energy Management – Sooner Unit - Pit ID 112069
Inspection Date: 08/28/2019



Photo # 4 – Petroleum impacted soil near culvert (tin horn) requiring closure under an approved eForm 27.