

Inspection Photos
Location Name: Jacobucci 23-32
Location ID: 333139



Pic 1 wrong operator number, and name

Pic 2

Inspection Photos
Location Name: Jacobucci 23-32
Location ID: 333139



Pic 3 wrong operator and number, stained soil near muffler, blue bucket not in containment/trash

Pic 4 stained sil by pumping unit motor, and below counterweight.