

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2019

Submitted Date:

09/05/2019

Document Number:

693600160**FIELD INSPECTION FORM**
 Loc ID 312149 Inspector Name: QUINT, CRAIG On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10487Name of Operator: SPRINGDALE PARTNERS LLCAddress: 3409 MONTECLAIRE DRCity: SHERMAN State: TX Zip: 75092**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Stokes, Richard	903-815-4884	Richard.Stokes72@ymail.com	
Burn, Diana		diana.burn@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219049	WELL	AC	12/16/1992	STOW	075-05869	SPRINGDALE STORAGE 1	SI

General Comment:

Follow up inspection, No effort has been made to correct abatements (210.b., 603.f., 326) for inspections done 9/12/2017 #680001099, 7/2/2018 #680001776, 12/11/2018 #693600047

Location

Lease Road:			
Type	Access		
comment:	2 Track through pasture		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by well		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Invalid emergency contact number		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 08/09/2018

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds around equipment and across location.		
Corrective Action:	Comply with Rule 603.f .	Date:	07/19/2018

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Steel panels around wellhead		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Separator	# 1		
Comment:	In a metal shed		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Steel ring containment		
Corrective Action:		Date:	
Type: FWKO	# 1		
Comment:	In a cement containment		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 219049 Type: WELL API Number: 075-05869 Status: AC Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Shut in, Well was required to pass a Mechanical Integrity Test by 4/30/2017. No effort has been made to correct abatements.

Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan upon receipt of this inspection.

Date: 04/30/2017

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693600169	Inspection Photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4929483