

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/05/2019

Submitted Date:

09/05/2019

Document Number:

699300100

**FIELD INSPECTION FORM**

Loc ID 322551 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**  
OGCC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
10 Number of Comments  
3 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	<a href="#">All Inspections</a>
Gomez, Jason		jason.gomez@state.co.us	
Burn, Diana		diana.burn@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243835	WELL	TA	06/01/2019	GW	123-11627	UPRR 38 PAN AM "T" TRUE 1	TA

**General Comment:**

Location			
<b>Lease Road:</b>			
Type			
comment:	Location in the middle of a field and has no access road.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			Date:
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused Flowline plumbing on location.		
Corrective Action:	Comply with Rule 603.f 30 days for unused equipment when machinery is not required to remove equipment.		Date: <u>10/05/2019</u>
Type	WEEDS		
Comment:	Weeds growing on location		
Corrective Action:	Comply with Rule 603.f 10 days for weeds		Date: <u>09/15/2019</u>
Type	OTHER		
Comment:	Unused Flowline Riser LO but not Tagged		
Corrective Action:	Comply with Rule 603.f For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.		Date: <u>10/05/2019</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	AG fencing		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:			Date:

Type: Bradenhead	# 1	
Comment:	Appears to be Exposed at surface	
Corrective Action:		Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

<b>Inspected Facilities</b>			
Facility ID: <u>243835</u>	Type: <u>WELL</u>	API Number: <u>123-11627</u>	Status: <u>TA</u> Insp. Status: <u>TA</u>
<b>Idle Well</b>			
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned      Reminder: _____			
<div style="border: 1px solid black; padding: 5px;"> <p><b>Comment:</b> Well report show it as TA . Appears to have been shut in since June 2016. Flowline and Riser appear to have been disconnected and removed. Form 42 was submitted on 6/23/2017 Doc.# 401317065 Flowline Abandoned on 6/13/2017 per Rule 1105 It appears that their is no current MIT on record as required by Rule 326. MIT should be done ASAP</p> </div>			
Corrective Action: _____			Date: _____

<b>COGCC Comments</b>		
Comment	User	Date
<p>COGCC Inspection Report Summary                      On Thursday 9/5/19 at approximately 1200 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at the UPRR 38 Pan AM "T" True #1 Kerr McGee API #05-123-11627 in Weld County Colorado.</p> <p>While there, I observed TA wellsite.                      During this inspection the following compliance issues were observed:                      Housekeeping: Weeds growing on location. Comply with 603.f 10 days for weeds. CA date 9/15/2019 see photo #3 and 4.                      Housekeeping: Unused equipment on location. Comply with Rule 603.f 30 days for unused equipment when machinery is not required to remove equipment. CA date 10/5/2019. see photo #4                      Housekeeping: Unused riser on location LO but not tagged. Comply with Rule 603.f for unused, unmarked flowline risers 24 hrs. to lock out tag out. 30 days to remove rise CA date 10/5/2019. See photos #4 and 5                      Well report show it as TA. It appears to have been shut in since June 2016. Flowline and Riser appear to have been disconnected and removed.                      Form 42 was submitted on 6/23/2017 Doc. # 401317065 Flowline Abandoned on 6/13/2017 per Rule 1105.                      It appears that there is no current MIT on record as required by Rule 326. MIT should be done ASAP.                      Location is dry, weather is clear.                      A follow up on this site inspection needs to be conducted to ensure that all compliance issues are addressed to comply with COGCC rules.                      Continuing education COGCC Inspection Report Summary.                      This is a summary of inspection report.</p>	revasr	09/05/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300101	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4929876">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4929876</a>