

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/29/2019

Submitted Date:

08/30/2019

Document Number:

679705283

FIELD INSPECTION FORM

Loc ID 314716 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10654
Name of Operator: LASSO OIL & GAS LLC
Address: 3021 RIDGE RD #156
City: ROCKWALL State: TX Zip: 75032

Findings:

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Arauzo, Steven		steven.arauza@state.co.us	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Heil, John		john.heil@state.co.us	
Freeman, Kris	254-717-0435	kfreeman@31operating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229394	WELL	PR	04/01/2019	OW	103-07049	GEBAUER 14	PR

General Comment:

[COGCC Inspection Report Summary.](#)

On 8-30-2019 at approximately 15:30, inspector Rick Moran, conducted a routine inspection at Lasso Oil & Gas well Gebauer 14 in Rio Blanco county.

During this inspection the following compliance issues were observed:

- 1) Uncapped flowline riser. Photo 3. Complete by 9-30-2019.
- 2) Tank sign(s) missing capacity & contents. Photo 4 & 5. Complete by 10-28-2019.
- 3) Stained soil at well head. Photo 6. Complete by 9-30-2019.

Note: Gas venting directly to the atmosphere at well head. Photo 7.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679705283.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Located on lease road 0.2 miles from well head.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Missing capacity & contents on a sign.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/28/2019

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	_____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil at well head.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	09/30/2019

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Equipment:

Type: Deadman # & Marked	#		corrective date
	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	Uncapped flow line riser.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	09/30/2019

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	1	300 BBLs	STEEL AST		40.067890,-108.802330
Comment:					
Corrective Action:				Date:	
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate			Adequate	
Comment:					
Corrective Action:				Date:	
Venting:					
Yes/No	YES				
Comment:	Gas venting directly to the atmosphere through 2 holes on top of the casing plate.				
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 229394 Type: WELL API Number: 103-07049 Status: PR Insp. Status: PR

Producing Well

Comment: [Pump jack idle at time of inspection.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action: Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: NO Pit ID: _____ Lat: 40.067950 Long: -108.802370

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action Date: _____

Fencing:

Fencing Type: Wildlife Fencing Condition: Adequate

Comment:

Corrective Action Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402163101	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4926279
679705284	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4926260