

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/05/2019

Submitted Date:

09/05/2019

Document Number:

679705343

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 315110 _____ Moran, Rick _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10027

Name of Operator: C & J FIELD SERVICES

Address: 3650 COUNTY RD #2

City: RANGELY State: CO Zip: 81648

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,	970-629-5161	candjfield@centurytel.net	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230272	WELL	PR	10/12/2004	OW	103-07931	HARRISON-SMITH-GOV'T 3	PR

General Comment:

COGCC Inspection Report Summary.

On 9-5-2019 at approximately 10:30, inspector Rick Moran, conducted a routine well inspection at C & J Field Services well Harrison Smith 3 in Rio Blanco county.

No corrective actions were identified.

Note: Well venting casing gas. A 3 cubic foot bag filled with gas in 80 minutes. Photos 2, 3 & 4.

This is a summary of inspection report 679705343.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911 label at tank battery located nearest well Harrison Smith 2 (05-103-01122)

Corrective Action:

Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:				corrective date
Type: Submersible Pump	# 1			
Comment:				
Corrective Action:			Date:	
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	YES		
Comment:	Well venting casing gas. A 3 cubic foot bag filled with gas in 80 minutes.		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	230272	Type:	WELL	API Number:	103-07931	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Pump jack idle at time of inspection.								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679705344	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4929929