

**Inspection Photos**  
**Location Name: Marvin E Schutt Unit #1**  
**Location ID: 318480**



**Photo 1 Culvert to access road to location inlet appears to be plugged and ditch not maintained to culvert. Part of culvert has been removed.**



**Photo 2 middle of culvert had been damaged prior to part of culvert being removed clearly see weeds growing in culvert.**

**Inspection Photos**  
**Location Name: Marvin E Schutt Unit #1**  
**Location ID: 318480**



**Photo 3 Culvert to access road to location outlet is plugged and exposed culvert not properly covered.**



**Photo 4 What appears to be the Braden head piping Mechanical issue: 1/4 inch line has been removed and is laying on ground.**

**Inspection Photos**  
**Location Name: Marvin E Schutt Unit #1**  
**Location ID: 318480**



**Photo 5 PU and WH sign**



**Photo 6 WH is approx. 90 ft from resident to the North and approx. 45ft from electric panel. Debris: dead weeds around electric panel.**

**Inspection Photos**  
**Location Name: Marvin E Schutt Unit #1**  
**Location ID: 318480**



**Photo 7 WH is approx.. 115ft from resident to the east.**



**Photo 8 WH is approx.. 200ft from resident to the North east.**

**Inspection Photos**  
**Location Name: Marvin E Schutt Unit #1**  
**Location ID: 318480**



**Photo 9 Access road to location.**



**Photo 10 Access road from county road to location.**