

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/06/2019

Submitted Date:

09/06/2019

Document Number:

693501287

FIELD INSPECTION FORM

 Loc ID 318480 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 46290
 Name of Operator: KP KAUFFMAN COMPANY INC
 Address: 1675 BROADWAY, STE 2800
 City: DENVER State: CO Zip: 80202
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241373	WELL	PR	05/07/1977	OW	123-09162	MARVIN E. SCHUTT UNIT 1	PR

General Comment:

Inspected Facilities

Facility ID: 241373 Type: WELL API Number: 123-09162 Status: PR Insp. Status: PR

Complaint

Comment: Inspection in response to complaint.
 Field Inspector Assigned: Randy Silver
 Complaint Received
 Date: 08-29-2019
 Complaint Contacted:
 Date: 08-29-2019 Time: 2:00PM in person
 Location ID #318480
 Inspection Document # 693501280
 Complaint Document #200448021
 Nature of Complaint: Dust/ lease road
 Field Inspector Actions:
 On 08-30-2019, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to Dust/lease road. The complainant stated the issues were occurring on lease road to property.
 On 08-29-2019, I attempted to make contact with the complainant who indicated that on 8-29-19 complainant has several concerns with KPK's operations of wells in area of complainants home.
 I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I was not able to see any oil and gas associated vehicles on lease road. I did observe road was dry. Access road to well site Marvin E Schutt Unit #1 also has BMP Corrective action witch are listed in my Inspection Document.
 Homeowners on associated lease road off county road 19 would like to be involved when KPK does do maintenance on access road as land owners have paid for the gravel and the installation.
 See inspection document #693501280 per my inspection.
 I observed what appeared to be violations of COGCC rules at the time of the inspection. All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
See doc#693501280 for full inspection	silverr	09/06/2019