

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/05/2019

Submitted Date:

09/06/2019

Document Number:

687905482**FIELD INSPECTION FORM**

Loc ID 313588 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 6720Name of Operator: ROBERT L BAYLESS PRODUCER LLCAddress: 621 17TH ST STE 2300City: DENVER State: CO Zip: 80293**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Thomas, John	505-326-2659	jthomas@rlbayless.com	all inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271345	WELL	PR	09/07/2007	GW	083-06609	NORTH MAIL TRAIL 2	PR

**General Comment:**

[Site inspection and equipment inventory with photos at the end of this report.](#)

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Labels/placards posted on tanks.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign posted at pumpjack.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Contact information posted on sign.

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bird Protectors	# 2		
Comment:	On flare and separator stacks.		
Corrective Action:		Date:	
Type: Flare	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	
Type: Flow Line	# 5		
Comment:	1-2" flowline from wellhead to separator. 1-2" flowline from separator dump valve to produced water tank. 1-2" flowline from separator to crude oil storage tanks. 1-2" flowline from separator to meter run. 1-2" flowline from separator to flare unit fuel gas and pumpjack engine fuel gas.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		

Comment:	Natural gas engine on pumpjack with stained soil around engine on the ground.		Date:	10/06/2019
Corrective Action:	Clean-up and dispose stained soil per Rule 1002.f.		Date:	10/06/2019
Type: Deadman # & Marked	# 4			
Comment:			Date:	
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:			Date:	
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Berm maintenance inadequate. Portions of berm washed away from rain events and burrows along sections from wildlife.			
Corrective Action:	Repair berms or other secondary containment devices per Rule 906.d.(1).			Date: 10/06/2019

**Venting:**

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	271345	Type:	WELL	API Number:	083-06609	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing.								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	Spill prevention for engine oil daytank.
Compaction	Pass	Compaction	Pass			
				Material Handling And Spill Prevention	Pass	Spill prevention for fuel gas knockout pot.

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905491	Stained soil around engine.	<a href="#">DSCN4334.JPG</a>
687905492	Inadequate secondary containment.	<a href="#">DSCN4340.JPG</a>