

COGCC Inspection Photos 08/29/2019 & 9/3-4/2019

Location: Held 12-1418 Off Location Flowline

Well API 123-18653

Spill ID # 467174



Signage at tank battery.



View release point marked at irrigation ditch; off location flowline marked with pin flags. View NW toward wellhead.

COGCC Inspection Photos 08/29/2019 & 9/3-4/2019

Location: Held 12-1418 Off Location Flowline

Well API 123-18653

Spill ID # 467174



Off location flowline marked with pin flags; View SE toward battery from spill point at irrigation ditch.



Impacted irrigation ditch from spill; booms deployed. View South from WCR 46.

COGCC Inspection Photos 08/29/2019 & 9/3-4/2019

Location: Held 12-1418 Off Location Flowline

Well API 123-18653

Spill ID # 467174



Impacted stock pond; booms deployed. View North toward WCR 46.



Spill response in progress; Impacted stock pond; booms deployed. View South toward Hillsboro Ditch.

COGCC Inspection Photos 08/29/2019 & 9/3-4/2019

Location: Held 12-1418 Off Location Flowline

Well API 123-18653

Spill ID # 467174



**Excavation at release point; flowline being exposed.
Impacted soils observed.**



**Section of flowline removed (Yellow Jacket); Coating has
been stripped back to expose corrosion hole.**

COGCC Inspection Photos 08/29/2019 & 9/3-4/2019

Location: Held 12-1418 Off Location Flowline

Well API 123-18653

Spill ID # 467174



**Failure point identified; External corrosion hole found.
Coating has been removed.**



Cut ends of flowline in excavation threaded and bull plugged. Flowline is scheduled to be removed/ replaced.