

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/06/2019

Submitted Date:

09/06/2019

Document Number:

693501288

### FIELD INSPECTION FORM

Loc ID 318480 Inspector Name: Silver, Randy On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 3 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	<a href="#">All inspections</a>
Adamczyk, Megan		megan.adamczyk@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241373	WELL	PR	05/07/1977	OW	123-09162	MARVIN E. SCHUTT UNIT 1	PR

**General Comment:**

**Inspected Facilities**

Facility ID: 241373 Type: WELL API Number: 123-09162 Status: PR Insp. Status: PR

**Complaint**

Comment: Inspection in response to complaint.  
 Field Inspector Assigned: Randy Silver  
 Complaint Received  
 Date: 09-3-2019  
 Complaint Contacted:  
 Date: 08-29-2019 Time: 2:00PM in person  
 Location ID #318480  
 Inspection Document # 693501280  
 Complaint Document #200448040  
 Nature of Complaint: Safety/ maintenance  
 Field Inspector Actions:  
 On 09-3-2019, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to Safety/Maintenance. The complainant stated the issues were occurring outside of multiple resident's homes.  
 On 09-03-2019, I attempted to make contact with the complainant who indicated that Pump jack on Marvin E Schutt Unit #1 is located in close proximity to two homes. Both homes have children either living or visiting at homes Ages 1 through 8 years of age. Pump jack has no safety measure to protect humans from injury. Also stated issue with weeds.  
 I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I observed one resident was approx. 100 ft from wellhead and the other was approx... 90ft from wellhead. Electric panel was approx... 45ft to closest resident. Well head and Pumping unit has barbwire fence witch is inadequate. Electric panel has small steel tubing guard witch is inadequate. Other corrective actions were observed and I have stated all corrective action in my field inspection report.  
 Weather conditions: Clear and location is dry  
 See inspection document #693501280 per my inspection.  
 At time of inspection corrective actions per COGCC rules were observed.  
 All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
See Doc#693501280 for full inspection.	silverr	09/06/2019