

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/05/2019

Submitted Date:

09/08/2019

Document Number:

689703506

FIELD INSPECTION FORM

Loc ID 311584 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
14 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: PO BOX 370
 City: PARACHUTE State: CO Zip: 81635

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211299	WELL	PR	11/10/1997	GW	045-07058	UNOCAL GM 21-2	PR
281724	WELL	PR	05/01/2006	GW	045-11502	SOLVAY CHEMICALS INC GM 253-2	PR
281725	WELL	PR	06/03/2006	GW	045-11503	SOLVAY CHEMICALS INC GM 421-2	PR
281727	WELL	PR	06/02/2006	GW	045-11504	SOLVAY CHEMICALS INC GM 521-2	PR

General Comment:
 COGCC Inspection Report Summary
 On Thursday 09/05/2019 at approximately 1230 hrs, I, Inspector Mike Longworth, conducted a Follow up field inspection at TEP ROCKY MOUNTAIN LLC, UNOCAL GM 21-2 at Location # 311584 in Garfield County, Colorado
 During this inspection the following possible compliance issues were observed:
 Weed debris along flowline from separators to tank. Dead weed debris along perimeter of location.
 Comply with Rule 603.f.
 C.A. Date 10/09/2019
 Location has been bladed and subsided pipelines have back filled. Dirt work looks incomplete. Excess dirt and weed debris piled around perimeter of location. No apparent storm water BMPs.
 Install or repair required BMPs per Rule 1002.f.
 C.A. Date 10/09/2019

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Capacity has been repaired to 80 bbl tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign is discolored and peeling.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds were partially cleared. Dead debris and excess dirt piled around perimeter of location.		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	Unused pipe manifold was removed from location.		
Corrective Action:		Date:	
Type	DEBRIS		
Comment:	Weed debris along flowline from separators to tank. Dead weed debris along perimeter of location.		
Corrective Action:	Comply with Rule 603.f.	Date:	10/09/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Bird Protectors	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:	Separators and tank battery on separate location from wells. No location id. found for battery location.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<100 BBLS	STEEL AST		39.470570,-108.077080

Comment:	Separators and tank battery on separate location from wells. No location id. found for battery location. Original tank battery has been removed.		
----------	--	--	--

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>211299</u>	Type:	<u>WELL</u>	API Number:	<u>045-07058</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing well</u>								
Corrective Action:								Date:	
Facility ID:	<u>281724</u>	Type:	<u>WELL</u>	API Number:	<u>045-11502</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing well</u>								
Corrective Action:								Date:	
Facility ID:	<u>281725</u>	Type:	<u>WELL</u>	API Number:	<u>045-11503</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing well</u>								
Corrective Action:								Date:	
Facility ID:	<u>281727</u>	Type:	<u>WELL</u>	API Number:	<u>045-11504</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing well</u>								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Location has been bladed and subsided pipelines have back filled. Dirt work looks incomplete. Excess dirt and weed debris piled around perimeter of location. No apparent storm water BMPs.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 10/09/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689703514	Inspection 689703506 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4931537