

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/06/2019

Submitted Date:

09/09/2019

Document Number:

679705372**FIELD INSPECTION FORM**Loc ID 333342 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10342Name of Operator: WOODARD\* SANDRA KAddress: 602 OURAY AVENUECity: GRAND JUNCTION State: CO Zip: 81501**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
,	970-261-6589	3oilwells@gmail.com	
,	970-261-6589	zandi@bresnan.net	
Arauza, Steven		steven.arauza@state.co.us	
Heil, John		john.heil@state.co.us	
Pesicka, Conor	970-415-0789	conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229445	WELL	SI	06/01/2019	OW	103-07101	STAGNER 2	SI
229705	WELL	SI	06/01/2019	OW	103-07362	STAGNER 6	SI

**General Comment:**[COGCC Inspection Report Summary.](#)

On 9-6-2019 at approximately 15:30, inspector Rick Moran, conducted a routine inspection at Sandra K Woodard well Stagner 2 and 6 in Rio Blanco county.

During this inspection the following compliance issues were observed:

- 1) Well head signs illegible. Letters are peeling off. Photos 3 & 6. Complete by 11-9-2019.
- 2) Stained & oily soil at multiple locations. Photos 8, 11, 12, 13. Complete by 10-9-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Note: Casing open to atmosphere on wells Stagner 2 & 6. No gas odor detected at Stagner 6 for which the casing vent opening is primarily plugged with dirt. Stagner 2 filled a 3 cubic ft bag in 7 minutes and the gas odor was detected 40 ft from the well head by the inspector. No odor detected at P&A well Stagner 3. Photos 5, 9, 15.

Wells are located 800 ft from the nearest residence and 900 ft from the White River.

This is a summary of inspection report 679705372.

**Location**Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well head signs are not fully legible. Letters are peeling off signs.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	11/09/2019
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911	
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	OTHER		
Comment:	Pump jack, fencing, & wood on NW edge of location. Appears to be pump jack from well Stagner 2.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Stained & oily soil around well head at Stagner 6. Stained dirt pile at NW edge of location. Stained next to crude oil tank.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	10/09/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
----------	---	----------	------	---------	--------	--

CRUDE OIL	1	400 BBLs	STEEL AST		40.098550,-108.815940	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate					
Comment:						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	YES					
Comment:	Casing open to atmosphere on wells Stagner 2 & 6. No gas odor detected at Stagner 6 for which the casing vent opening is primarily plugged with dirt. Stagner 2 filled a 3 cubic ft bag in 7 minutes and the odor was detected 40 ft from the well head by the inspector. No odor detected at P&A well Stagner 3.					
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

**Inspected Facilities**Facility ID: 229445 Type: WELL API Number: 103-07101 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Pump jack removed from well head. Last recorded production May 2019.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 229705 Type: WELL API Number: 103-07362 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Last recorded production May 2019.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No apparent significant soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679705376	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4931843">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4931843</a>