

Inspection Photos
Location Name: Eagle Hill 1-32
Location ID: 466705



Photo 1. Overview of location with conductor rig and main rig on location. Photo facing east.



Photo 2. Overview of location facing southeast.



Inspection Photos
Location Name: Eagle Hill 1-32
Location ID: 466705



Photo 3. Surface disturbance increase, trucks driving/parking on side of location.



Photo 4. Surface disturbance increase, vehicles parked on side of location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Eagle Hill 1-32
Location ID: 466705



Photo 5. Surface disturbance increase, trucks driving/parking on side of access road. Gravel added to access road, no stormwater controls on perimeter of road.



Photo 6. Gravel added to access road, no stormwater controls on perimeter of road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Eagle Hill 1-32
Location ID: 466705



**Photo 7. Wattles installed on some of location perimeter.
Wattles not trenched.**



**Photo 8. Wattles installed on some of location perimeter.
Wattles not trenched.**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Eagle Hill 1-32
Location ID: 466705



Photo 9. Wattles installed on east side of drainage crossing. Wattles not trenched. No other controls observed.



Photo 10. No stormwater controls observed on west, uphill, side of drainage crossing.

