

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-08128
Date: 8-29-2019



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of kochia weeds around wellhead.



Photo 3. View of erosional channeling at the well pad entrance facing eastward.



Photo 4. View of erosional tunnel within the southeastern fill slope.



Photo 5. View of erosional downcutting along both sides of culvert along shared access road. This is compromising the integrity of the access road and needs to be repaired.



Photo 6. View of reference area facing eastward. Vegetation is comprised of pinyon juniper woodland.