

Inspection Photos
Operator: Vernon E Faulconer
Location/API #: 067-06289
Date: 8-29-2019



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of musk thistle infestation within the southwestern project area.



Photo 3. View of dense musk thistle rosettes within the southwestern project area.



Photo 4. View of the southern fill slope from the southeastern edge facing northwestward.



Photo 5. View of erosional tunnels within the northwestern fill slope, near the well pad entrance.



Photo 6. View of area in the northeastern project area that diverted stormwater flows off of the well pad. Evidence sedimentation, and erosional channeling observed.



Photo 7. View of erosional channeling and sedimentation on the access road.



Photo 8. View of erosional downcutting along both sides of culvert along access road. This is compromising the integrity of the access road and needs to be repaired.



Photo 9. View of reference area facing eastward. Vegetation is comprised of pinyon juniper woodland.