

Inspection Photos
Location Name: Hladky O'Gorman #3
Location ID: 332971



Photo 1 WH sign faded not legible. Well head can visible see and hear what appears to be gas leaking in and around packing.

Photo 2 location pic **WEEDS**.

Inspection Photos
Location Name: Hladky O'Gorman #3
Location ID: 332971



Photo 3 Unused equipment: storage tank stairs. **WEEDS.**

Photo 4 Unused equipment: unmarked not LOTO risers. **WEEDS.**

Inspection Photos
Location Name: Hladky O'Gorman #3
Location ID: 332971



Photo 5 TNK BTRY. BTRY sign faded not legible. **WEEDS.**



Photo 4 TNK BTRY **WEEDS.**

Inspection Photos
Location Name: Hladky O'Gorman #3
Location ID: 332971



Photo 6 TNK BTRY secondary containment BMP in disrepair sediment being carried of BPM and into field. **WEEDS.**

Photo 7 TNK BTRY secondary containment BMP in disrepair sediment being carried of BPM and into field. **WEEDS.**

Inspection Photos
Location Name: Hladky O'Gorman #3
Location ID: 332971



Photo 7 Re-circ pump **WEEDS.**



Photo 8 Separator **WEEDS.**

Inspection Photos
Location Name: Hladky O'Gorman #3
Location ID: 332971



Colorado Oil and Gas Conservation Commission
Sep 9, 2019 11:34:50



Colorado Oil and Gas Conservation Commission
Sep 9, 2019 12:03:54

Photo 9 Mechanical issue and stained soil inside separator.

Photo 10 Trash: Separator door laying on ground next to separator. **WEEDS.**

Inspection Photos
Location Name: Hladky-O'Gorman #3
Location ID: 332971



Photo 11 Unused equipment: Electric panel Meter has been pulled.



Photo 12 Unused equipment: PU is not inoperable electric meter has been pulled PU cannot run **WEEDS.**