

Inspection Photos
Location Name: William Lansdown #1
Location ID: 317613



Photo #1 WH sign



Photo #2 WH PJ

Inspection Photos
Location Name: William Lansdown #1
Location ID: 317613



Photo #3 Electric panel removed conduit and wire Exposed at ground level

Photo #4 weeds growing around Control panel

Inspection Photos
Location Name: William Lansdown #1
Location ID: 317613



Photo #5 Unused casing along fence



Photo #6 Hoz separator

Inspection Photos
Location Name: William Lansdown #1
Location ID: 317613



Photo #7 Vert. Sep. building



Photo #8 unmarked no LOTO on riser in Vert. Sep. building

Inspection Photos
Location Name: William Lansdown #1
Location ID: 317613



Photo #9 unused riser no LOTO




Photo #10 unused riser no LOTO

Inspection Photos
Location Name: William Lansdown #1
Location ID: 317613




Photo #11 Gas meter run

Photo #12 Gas meter appears to have been last calibrated on 4/4/2012

Inspection Photos
Location Name: William Lansdown #1
Location ID: 317613



Photo #13 Prod. water tank berm not adequate and in disrepair.

Photo #14 TB

Inspection Photos
Location Name: William Lansdown #1
Location ID: 317613



Photo #15 Prod. water tank berm not adequate and in disrepair.