

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	What appears to be unused casing along fence line		
Corrective Action:	Comply with Rule 603.f	Date:	03/14/2019
Type	UNUSED EQUIPMENT		
Comment:	Per Doc. 685101443 605.d the electrical panel has been removed but the conduit and wires were cut at ground level and are exposed.		
Corrective Action:	Comply with Rule 603.f 30 days for unused equipment when machinery is not required to remove the equipment. 90 days for unused equipment when machinery is required to remove the equipment	Date:	03/14/2019
Type	WEEDS		
Comment:	Weeds growing on location		
Corrective Action:	Comply with Rule 603.f 10 days for weeds	Date:	09/19/2019
Type	UNUSED EQUIPMENT		
Comment:	unused and unmarked no LOTO on flowline risers		
Corrective Action:	For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.	Date:	03/14/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
------	-----------	--	--

Comment:	Fabricated steel poles	Date:	
Corrective Action:		Date:	
Type	OTHER		
Comment:	Flowline Fab. steel pole	Date:	
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Does not appear to be plumbed to surface		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLS	PBV CONCRETE		,	
Comment:						
Corrective Action:						Date: 03/14/2019

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	50bbl	

Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate		
Comment: Per Doc. # 688401334 inadequate berm around tank has not been addressed						
Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).					Date:	03/14/2019
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 239561 Type: WELL API Number: 123-07348 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 9/9/19 at approximately 1300 I, Inspector Robbie Revas, Conducted a follow up on-site inspection (5) Per Doc. # 685101443, 685101039, 685100792 and 688401334 at the William D Lansdown #1 KP Kauffman, at API #05-123-07348 in Weld County Colorado. While there, I observed a SI Well and tank battery. During this inspection the following possible compliance issues were observed: Housekeeping: Unused csg. On loc. Per Doc. # 685101443 CA 603.f has not been addressed. CA date 3/14/2019 See attached photo #5. Housekeeping: Control panel knocked over Per Doc. # 685101443 CA 605.d appears to have been removed. Conduit and wire has been left exposed at ground level, comply with Rule 603.f. unused equipment. CA date 3/14/2019 see photo # 3 Housekeeping: Unused unmarked Flow line risers no LOTO. Per Doc. # 685101443, 685101039, 685100792 and 688401334, have not been addressed under Rule 1103 and has been added to Rule 603.f For unused, unmarked risers 24 hrs. to LOTO. 30 days to remove riser.CA date 3/14/2019 see photos # 8, 9 and 10. Tanks:Per Doc. # 688401334 Repair or install berms or other secondary containment devices per Rule 605.a.(4) was addressed on the crude oil tank berm but not on the produced water tank berm. CA date 3/14/2019 see photo #13 Housekeeping: Weeds growing on location. Comply with Rule 603.f 10 days for weeds. 9/19/2019 Location is dry, weather is clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	09/09/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300121	Location pics.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4932579