

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/21/2019

Submitted Date:

09/03/2019

Document Number:

690900074**FIELD INSPECTION FORM**Loc ID 414031 Inspector Name: FISCHER, ALEX On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10619Name of Operator: INSPIRE OIL & GAS INCAddress: 1400 BROADFIELD BLVD SUITE 600City: HOUSTON State: TX Zip: 77084**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments8 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ritz, Bo	713-269-4969	britz@inspireoilandgas.com	
Neidel, Kris		kris.neidel@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Waldron, Emily		emily.waldron@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412127	WELL	PR	10/20/2012	GW	057-06490	Silver Spur Minerals 35-2H	EI

General Comment:

On August 21, 2019 COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of Inspire Oil and Gas Inc's Silver Spur Minerals 35-2H, API 05-057-06490. Weather was sunny and temperature 67 degree F. For the most recent field inspection report of this facility, please refer to document #689800259. Note: The corrective action (CA) dates of document #689800259 still remain.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) or battery		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	10/03/2019
Type	OTHER		
Comment:	Sign not posted or information inaccurate at entrance off of Hwy 14.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	10/03/2019
Type	BATTERY		
Comment:	Sign not posted or information inaccurate at well(s) or battery. Note: Produced water tanks signage, labeling, and placarding illegible.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	10/03/2019

Emergency Contact Number:

Comment:	Location sign off of Hwy 14. (Note: phone number was not active on 9/3/2019). Well sign. (Note: phone number was not active on 9/3/2019). Produced water tanks signage, labeling, and placarding illegible.		
Corrective Action:	Install sign to comply with Rule 210.d. Install sign to comply with Rule 210.e.	Date:	10/04/2019

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Tubing and misc equipment stored on Location.		
Corrective Action:	Comply with Rule 603.f.	Date:	10/13/2017

Overall Good: ☐**Spills:**

Type	Area	Volume		
Condensate	Tank	<= 1 bbl		
Comment:	Tank 0030, staining beneath hammer unions.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a.			Date: 09/04/2019

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient		Inadequate

Comment: Berm is not consolidated.Corrective Action: Repair or install berms or other scndary containment devices per Ruls 605.a.(4).Date: 10/13/2017

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,

Comment:

Corrective Action:

Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient		Inadequate

Comment: Berm is not consolidated.Corrective Action: Repair or install berms or other scndary containment devices per Ruls 605.a.(4).Date: 10/13/2017Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Environmental**Spills/Releases:**

Type of Spill: _____	Estimated Spill Volume: _____
Comment: _____	
Corrective Action: _____	Date: _____
Reportable: _____	GPS: Lat _____ Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____

Water Well Complaint:

		Lat	Long
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	_____

Field Parameters:

Sample Location: _____	Comment: _____
------------------------	----------------

COGCC Comments

Comment	User	Date
Note: The corrective action (CA) dates of document #689800259 still remain. The operator shall immediately address the drips from the leaking hammer unions.	fischera	09/03/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402164132	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4927076
690900075	INSP Photo Silver Spur Min 0505706490 20190821ajf	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4927074