

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/10/2019

Submitted Date:

09/10/2019

Document Number:

689703521

FIELD INSPECTION FORM

Loc ID 335905	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 17 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285534	WELL	PR	10/26/2007	GW	045-12514	N. PARACHUTE EF03B19 D19A595	PR
286632	WELL	PR	01/27/2014	GW	045-12712	N. PARACHUTE EF04A D19A595	PR
286633	WELL	PR	09/07/2006	GW	045-12711	N. PARACHUTE EF08B D19A 595	PR
286634	WELL	PR	09/07/2006	GW	045-12710	N.PARACHUTE EF01B D19A 595	PR
286635	WELL	PR	09/07/2006	GW	045-12709	N. PARACHUTE EF01D D19A 595	PR
286636	WELL	PR	09/07/2006	GW	045-12708	N. PARACHUTE EF02D D19A 595	PR
286637	WELL	PR	09/07/2006	GW	045-12707	N.PARACHUTE EF02B D19A 595	PR
286638	WELL	PR	09/07/2006	GW	045-12706	N. PARACHUTE EF03C D19A 595	PR
286639	WELL	PR	02/01/2011	GW	045-12705	N. PARACHUTE EF03D D19A 595	PR
286640	WELL	PR	09/11/2006	GW	045-12704	N. PARACHUTE EF07B D19A 595	PR
286641	WELL	PR	09/11/2006	GW	045-12703	N. PARACHUTE EF01D-24 D19A 5	PR
286721	WELL	PR	09/14/2006	GW	045-12772	N. PARACHUTE EF03B D19A 595	PR

General Comment:

COGCC Inspection Report Summary

On Tuesday 09/10/2019 at approximately 1500 hrs, I, Inspector Mike Longworth, conducted a field inspection at CAERUS PICEANCE LLC N.PARACHUTE-65S95W 19NENW Location #335905 in Garfield County, Colorado

During this inspection the following possible compliance issues were observed:

3 unmarked deadmen on location.

Install proper guy line markers per Rule 1003.a

C.A. Date 09/26/2019

Subsidence of rathole at well EF03B.

Install or repair required BMPs per Rule 1002.f.

C.A. Date 10/11/2019

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 3		corrective date
Comment:	3 unmarked deadmen on location.		
Corrective Action:	Install proper guy line markers per Rule 1003.a		Date: 09/26/2019

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	80 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	285534	Type:	WELL	API Number:	045-12514	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	286632	Type:	WELL	API Number:	045-12712	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	286633	Type:	WELL	API Number:	045-12711	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	286634	Type:	WELL	API Number:	045-12710	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	286635	Type:	WELL	API Number:	045-12709	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	286636	Type:	WELL	API Number:	045-12708	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	286637	Type:	WELL	API Number:	045-12707	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	286638	Type:	WELL	API Number:	045-12706	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	286639	Type:	WELL	API Number:	045-12705	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	286640	Type:	WELL	API Number:	045-12704	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	286641	Type:	WELL	API Number:	045-12703	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	286721	Type:	WELL	API Number:	045-12772	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Subsidence of rathole at well EF03B.](#)Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 10/11/2019

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689703522	Inspection 689703521 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934261