

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/10/2019

Submitted Date:

09/11/2019

Document Number:

679705397**FIELD INSPECTION FORM**

|  |                                |   |                   |   |
|--|--------------------------------|---|-------------------|---|
| Loc ID<br>315966   | Inspector Name:<br>Moran, Rick | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | <b>Status Summary:</b><br><input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION<br><input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED<br><input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED<br><br><b>Findings:</b><br>6 Number of Comments<br>2 Number of Corrective Actions<br><input checked="" type="checkbox"/> Corrective Action Response Requested |
| <b>Operator Information:</b><br>OGCC Operator Number: <u>16700</u><br>Name of Operator: <u>CHEVRON USA INC</u><br>Address: <u>100 CHEVRON USA INC</u><br>City: <u>RANGELY</u> State: <u>CO</u> Zip: <u>81648</u> |                                |   |                   | <b>ANY CORRECTIVE ACTION(S) FROM<br/>PREVIOUS INSPECTIONS THAT HAVE NOT<br/>BEEN ADDRESSED ARE STILL APPLICABLE</b>   |

**Contact Information:**

| Contact Name    | Phone        | Email                      | Comment |
|-----------------|--------------|----------------------------|---------|
| Sanford, Anita  |              | atlx@chevron.com           |         |
| Kellerby, Shaun | 970-712-1248 | shaun.kellerby@state.co.us |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 231817      | WELL | PR     | 02/01/2019  | OW         | 103-09488 | F V LARSON "B" 27X | PR          |

**General Comment:**

COGCC Inspection Report Summary.

On 9-10-2019 at approximately 18:00, inspector Rick Moran, conducted a routine inspection at Chevron well F.V. Larson B27X in Rio Blanco county.

During this inspection the following compliance issues were observed:

- 1) Trash. Photo 2. Complete by 10-11-2019.
- 2) Unused rods. Photo 3. Complete by 10-11-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679705397.

**Location**Overall Good: ☒

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             |          |       |  |
| Corrective Action:   |          | Date: |  |

|                           |     |       |  |
|---------------------------|-----|-------|--|
| Emergency Contact Number: |     |       |  |
| Comment:                  | 911 |       |  |
| Corrective Action:        |     | Date: |  |

|                           |                          |       |            |
|---------------------------|--------------------------|-------|------------|
| <b>Good Housekeeping:</b> |                          |       |            |
| Type                      | UNUSED EQUIPMENT         |       |            |
| Comment:                  | Unused rods on location. |       |            |
| Corrective Action:        | Comply with Rule 603.f . | Date: | 10/11/2019 |
| Type                      | TRASH                    |       |            |
| Comment:                  | Unused wood on location. |       |            |
| Corrective Action:        | Comply with Rule 603.f . | Date: | 10/11/2019 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                          |     |       |                 |
|--------------------------|-----|-------|-----------------|
| <b>Equipment:</b>        |     |       | corrective date |
| Type: Deadman # & Marked | # 4 |       |                 |
| Comment:                 |     |       |                 |
| Corrective Action:       |     | Date: |                 |
| Type: Submersible Pump   | # 1 |       |                 |
| Comment:                 |     |       |                 |
| Corrective Action:       |     | Date: |                 |

|                    |    |       |  |
|--------------------|----|-------|--|
| <b>Venting:</b>    |    |       |  |
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

|                             |                            |                       |            |                  |
|-----------------------------|----------------------------|-----------------------|------------|------------------|
| <b>Inspected Facilities</b> |                            |                       |            |                  |
| Facility ID: 231817         | Type: WELL                 | API Number: 103-09488 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>       |                            |                       |            |                  |
| Comment:                    | Producing well on subpump. |                       |            |                  |
| Corrective Action:          |                            |                       |            | Date:            |

|  |
|--|
|  |
|--|

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            | Pass            |                         |                       |               |                          |         |

Comment: [No apparent significant soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 679705398    | inspection photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934481">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934481</a> |