

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/06/2019

Submitted Date:

09/06/2019

Document Number:

679601518**FIELD INSPECTION FORM**Loc ID 432887 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**17 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432883	WELL	PR	07/14/2015	OW	123-37336	Alm 33U-234	PR
432907	WELL	PR	07/13/2015	OW	123-37352	ALM 33V-314	PR
432924	WELL	PR	07/13/2015	OW	123-37360	Alm 33V-414	PR
432926	WELL	PR	07/14/2015	OW	123-37362	Alm 33U-404	PR
446707	TANK BATTERY	AC	07/18/2016		-	Alm 33V-HZ NORTH	AC

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate (x4)		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Battery near wellhead. See attached photo.		
Corrective Action:	Comply with Rule 603.f.	Date:	09/16/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel (x4)		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bradenhead	# 4		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with other tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLs	FIBERGLASS AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with other tanks.			

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	100 BBLs	BV FIBERGLASS			
Comment: Anchored (IN FLOOD PLAINS ACCORDING TO COGCC MAPS)						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment: Shares containment with crude oil tanks.					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	12	400 BBLs	STEEL AST		40.535600,-104.659100
Comment: Anchored (IN FLOOD PLAINS ACCORDING TO COGCC MAPS)					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: <u>432883</u>	Type: <u>WELL</u>	API Number: <u>123-37336</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>PR</u>				
Corrective Action:				Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>
Facility ID: <u>432907</u>	Type: <u>WELL</u>	API Number: <u>123-37352</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>PR</u>				
Corrective Action:				Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>
Facility ID: <u>432924</u>	Type: <u>WELL</u>	API Number: <u>123-37360</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>PR</u>				
Corrective Action:				Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>
Facility ID: <u>432926</u>	Type: <u>WELL</u>	API Number: <u>123-37362</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>PR</u>				
Corrective Action:				Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>
Facility ID: <u>446707</u>	Type: <u>TANK</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>AC</u>
<u>Producing Well</u>				
Comment: <u>PR</u>				
Corrective Action:				Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On Friday, September 6, 2019 at approximately 12:40, I, Inspector Brittani Santistevan, conducted an on-site inspection at ALM 33V-HZ NORTH PAD (PDC Energy), at location #: 432887 in WELD COUNTY Colorado. While there, I observed producing facility. During this inspection the following possible compliance issues were observed: 1. Appears to be some type of battery left inside fencing that contains wellhead. COMPLY WITH RULE 603.F. (Corrective Action Date: September 16, 2019) See attached photo #3 in individual wellhead photos (ALM 33U-234). A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> <p>Continuing Education Inspection.</p>	santistb	09/06/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679601519	Alm 33U-404	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934557
679601520	Alm 33U-234	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934558
679601521	Alm 33V-414	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934559
679601522	Location Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934560