

# Inspection Photos

API: 05-071-09797

Operator: XTO ENERGY

Inspection Date: 9/6/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-071-09797 | Date: 9/6/2019

## Inspection Photos



**Photo 1.** Facing west along the reclaimed access road. Perennial vegetation is uniformly established. This photo is near the NEW ELK #27-02 site.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-071-09797 | Date: 9/6/2019



## Inspection Photos



**Photo 2.** Facing west along the reclaimed access road. Perennial vegetation is uniformly established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09797 | Date: 9/6/2019



## Inspection Photos



**Photo 3.** Facing southwest along the reclaimed access road. Shrubs (Gambel oak) are reestablishing along the road. Arrow points to preexisting road that continues along the ridge.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09797 | Date: 9/6/2019



## Inspection Photos



**Photo 4.** Facing south along the reclaimed access road. Perennial vegetation is well established.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-071-09797 | Date: 9/6/2019



## Inspection Photos



**Photo 5.** Facing south along the reclaimed access road. Perennial vegetation is well established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09797 | Date: 9/6/2019



## Inspection Photos



**Photo 6.** Facing southeast at the end of the reclaimed access road. Perennial vegetation is well established. There was no location built at the NEW ELK #27-06 site.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-071-09797 | Date: 9/6/2019