

Inspection Photos

API: 05-071-09790

Operator: XTO ENERGY

Inspection Date: 9/6/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09790 | Date: 9/6/2019

Inspection Photos



Photo 1. Facing west along the reclaimed access road. Perennial vegetation is uniformly established. This photo is taken near the NEW ELK #27-08 site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09790 | Date: 9/6/2019

Inspection Photos



Photo 2. Facing west along the reclaimed access road. Perennial vegetation is uniformly established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09790 | Date: 9/6/2019

Inspection Photos



Photo 3. Facing southwest along the reclaimed access road. A preexisting road went through this area which can still be accessed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09790 | Date: 9/6/2019

Inspection Photos



Photo 4. Facing southwest along the reclaimed access road. A preexisting road went through this area which can still be accessed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09790 | Date: 9/6/2019

Inspection Photos



Photo 5. Facing west along the reclaimed access road. There was no location built at the NEW ELK #27-02 site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09790 | Date: 9/6/2019