

Inspection Photos

API: 05-071-09786

Operator: XTO ENERGY

Inspection Date: 9/6/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-09786 | Date: 9/6/2019

Inspection Photos



Photo 1. Facing west along the reclaimed access road. Perennial vegetation is uniformly established. This photo is taken near the NEW ELK #26-04 site.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-09786 | Date: 9/6/2019

Inspection Photos



Photo 2. Facing southwest along the reclaimed access road. Perennial vegetation is uniformly established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09786 | Date: 9/6/2019

Inspection Photos



Photo 3. Facing southwest along the reclaimed access road. Perennial vegetation is uniformly established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09786 | Date: 9/6/2019

Inspection Photos



Photo 4. Facing back toward the northeast along the reclaimed access road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 05-071-09786 | Date: 9/6/2019

Inspection Photos



Photo 5. Facing southwest along the reclaimed access road. Perennial vegetation is uniformly established. The site is located at the top of the ridge.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09786 | Date: 9/6/2019

Inspection Photos



Photo 6. Facing south toward the site. There was no location built at the NEW ELK #27-08 site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09786 | Date: 9/6/2019